



**Before picture of the living room.** The electricians did some rewiring and had to put several holes into the walls.

**After picture of the living room.** This is the finished work. The holes were re-mudded and the walls were repainted the original color.



**This is a before picture of the other section of the living room. Again, more holes from the electrical work.**





**This is the after.** The ceiling, trim, and walls were all repainted.

